COMPLETION CERTIFICATE

This is to certify that SMT.VIMAL VITTHALRAO VARADE AND SHRI. SANJAY VITTHALRAO VARADE @

Property No. :- 100/3

S.NO.:-

WARD No:- 01

Plot Area :- 4045.83 sq.mt.

B/A.:- 665.28 sq.mt.

Mojay : - WARUD

Tq.:- WARUD

Dist.:- AMRAVATI

have been 100 % completed the work of his building as per sanctioned plan

This Construction Work Belonging to Mrs. SMT.VIMAL VITTHALRAO VARADE AND SHRI. SANJAY VITTHALRAO VARADE is Mangal Karyalaya Ground Floor Construction Has Been Complted As Per The Sasction Drg.And Specation

Now This Building Using as a for Educational Building

Please accept it the COMPLETION report the construction work is under taken and Supervised by me.

So it is true to my knowledge.

Thanking you.

Place: Warud

10 03 201

NIT LS NMC LS

AR. NAVIN LANJEWAR





BUILDING CONSTRUCTION

D.V.GULHANE
Architectura Consultant &
Interior Decoractors Enggineers
& Contractors

OFFICE ADRESS:
M.No. 9422384654
Ring Road, Warud
Dist - Amravati

▼ CIVIL CONTRACTOR

▼ DEVELOPERS ▼

ESTIMATOR

▼ VALUAR ▼

COMPLETION CERTIFICATE

This is to certify that the construction work of the Commercial building belonging to

Name of Owner :-

SMT.VIMAL VITTHALRAO VARADE

SHRI. SANJAY VITTHALRAO VARADE

Property No. :- 100/3

S.NO.:-

WARD No:- 01

Plot Area :- 4045.83 sq.mt. G.F.B/up Area ::-1431.00 sq.mt.

F.F.B/up area - 663.10 sq.mt G.F. + F.F.Total B/up area- 2094.10 sq.mt

Mojay: - WARUD

Tq.:- WARUD

Dist. :- AMRAVATI

have been completed the work of his building

This Building Is use for Educational work

Please accept it the **COMPLETION** report the construction work is under taken and Supervised by me.

So it is true to my knowledge.

Thanking you.

Date -06-09-2012

Place: Warud

Seal/Sign

D. V. Gulhane
Architectural Consultant &
Engineer & Contractors, Warud

Mob-9422384654